Ship Name: ADMIRE Ship Type: General Dry Cargo Ship

IMO Number: 9124146 Flag: Panama

Date Detained: 8/31/99 Class Society: Nippon Kaiji Kyokai

Port: Long Beach, California Company(s): Owners, Operators or Managers

Olamar Navegacion, SA

Deficiencies: Code - Category Description

0740 - Pumps Vessel's emergency fire pump could not supply

an adequate supply of water to any fire

Ship Name: AGIOS MINAS Ship Type: General Dry Cargo Ship

IMO Number: 7413323 Flag: Panama

Date Detained: 8/31/99 Class Society: American Bureau of Shipping

Port: Galveston, Texas Company(s): Owners, Operators or Managers

Trinity Shipping Corp.

Deficiencies: Code - Category Description

2020 - Fire drills Vessel's crew was unable to demonstrate a

satisfactory fire drill.

2025 - Abandon ship drills Vessel's crew was unable to demonstrate a

satisfactory abandon ship drill.

0740 - Pumps Emergency fire pump was inoperable.

0135 - Minimum safe manning

certificate

Vessel was insufficiently manned.

Ship Name: AKA I Ship Type: General Dry Cargo Ship

IMO Number: 6819673 Flag: Panama

Date Detained: 8/4/99 Class Society: Panama Shipping Register

Port: Miami, Florida Company(s): Owners, Operators or Managers

Bellini Navigation Corp.

Deficiencies: <u>Code - Category</u> <u>Description</u>

0945 - Emergency lighting, etc No emergency lighting was provided for

liferaft embarkation stations.

No 15 ppm oily-water separator on the vessel.

0230 - Number/composition Vessel not manned in accordance with Safe

(manning) Manning Document.

0120 - Load lines No stability book on the vessel.

1430 - Auxiliary engines Ship service generators inoperable.

1730 - Oily-water separating

0936 - Steering gear

equipment

No tiller provided to operate the emergency

steering gear.

Ship Name: AMER THAMES Ship Type: Chemical Tankship

IMO Number: 8217180 Flag: Panama

Date Detained: 8/2/99 Class Society: Nippon Kaiji Kyokai

Port: New Orleans, Louisiana Company(s): Owners, Operators or Managers

Amer Shipping Ltd Seaton Navigation Ltd.

Deficiencies: Code - Category Description

0230 - Number/composition Chief engineer's license expired; and (manning) insufficient GMDSS operators.

0720 - Fire fighting equipment Emergency fire pump inoperative.

2020 - Fire drills Crew unable to conduct proper fire drill.

Ship Name: APPA Ship Type: Bulk Carrier

IMO Number: 8017188 Flag: Saint Vincent and the Grenadines

Date Detained: 8/10/99 Class Society: Polski Rejestr Statkow

Port: **Houston, Texas** Company(s): Owners, Operators or Managers

Brighton Shipping Corp.

Deficiencies: Code - Category Description

2525 - Masters responsibility and Officers and crew were unfamiliar with the

authority Safety Management System.

0750 - Fire prevention
 1240 - Cargo and other hatchways
 Bridge deck fire dampers were inoperable.
 Watertight integrity was compromised from

wasted, main deck cargo hold entrance trunks.

Ship Name: **DESPINA** Ship Type: **General Dry Cargo Ship**

IMO Number: 7387316 Flag: Liberia

Date Detained: 8/19/99 Class Society: Bureau Veritas

Port: Tampa, Florida Company(s): Owners, Operators or Managers

Lavrion Shipping and Trading

Deficiencies: Code - Category Description

0113 - Cargo ship safety radio Safety Radio Certificate expired.

0950 - Electric equipment in Hazardous, improperly maintained, electrical

installations throughout the vessel.

0735 - Personal equipment - fire Breathing apparatus for firemen's outfits

fighting inoperable.

1270 - Doors Main deck, watertight doors were improperly

maintained, and no longer watertight.

Ship Name: GREAT NANCY Ship Type: Bulk Carrier

IMO Number: 8010881 Flag: Panama

Date Detained: 8/20/99 Class Society: Lloyd's Register of Shipping

Port: Los Angeles, California Company(s): Owners, Operators or Managers

Great Nancy S.A.

Deficiencies: Code - Category Description

2020 - Fire drills The crew was unable to perform a satisfactory

fire drill.

Ship Name: HAI YU Ship Type: Refrigerated Cargo Carrier

IMO Number: 8319598 Flag: China

Date Detained: 8/12/99 Class Society: China Classification Society

Port: **Dutch Harbor, Alaska** Company(s): Owners, Operators or Managers

Liaoning Pelagic Fisheries Co.

Deficiencies: Code - Category Description

0720 - Fire fighting equipment Fire extinguishing equipment improperly

installed throughout the vessel.

0950 - Electric equipment in Electrical panels improperly maintained;

exposed and hazardously connected wiring.

2020 - Fire drills Failed fire drill.

Ship Name: HELLAS Ship Type: Bulk Carrier

IMO Number: 8010960 Flag: Liberia

Date Detained: 8/12/99 Class Society: Bureau Veritas

Port: Virginia Beach, Virginia Company(s): Owners, Operators or Managers

Crown Eagle Shipping Co.
Polembros Maritime Co., Ltd.

Deficiencies: <u>Code - Category</u> <u>Description</u>

2530 - Resources and Personnel The chief engineer was unable to demonstrate

knowledge of the ship's Safety Management

System.

0999 - Other (Safety In General) Wasted, leaking and damaged hydraulic oil

lines on the main deck.

0740 - Pumps Emergency fire pump did not produce

sufficient water pressure.

1499 - Other (Prop. & Aux. Lube oil piping was improperly maintained

Machinery) and leaking excessively into engine room bilge.

0299 - Other (Crew) Crew was unable to demonstrate proper

operation of emergency steering.

Ship Name: LA ESPERANZA Ship Type: Containership

IMO Number: 8918253 Flag: Liberia

Date Detained: 8/3/99 Class Society: Nippon Kaiji Kyokai

Port: Los Angeles, California Company(s): Owners, Operators or Managers

Rosex Company Ltd.

Deficiencies: Code - Category Description

0630 - Launch arrangt. for The starboard lifeboat releasing mechanism

survival craft would not operate properly.

ship drill.

Ship Name: MACEDONIA HELLAS Ship Type: Bulk Carrier

IMO Number: 7433464 Flag: Greece

Date Detained: 8/23/99 Class Society: American Bureau of Shipping

Port: New Orleans, Louisiana Company(s): Owners, Operators or Managers

Spyvag Shipping

Worldwide Ocean Chartering

Deficiencies: Code - Category Description

2020 - Fire drills

Orew unable to conduct proper fire drill.

Two ship service generators inoperable; one

generator prime mover had excessive fuel

Ship Name: MYKONOS Ship Type: Bulk Carrier

IMO Number: 7916595 Flag: Malta

Date Detained: 8/2/99 Class Society: Nippon Kaiji Kyokai

Port: Long Beach, California Company(s): Owners, Operators or Managers

Seabream Maritime Ltd

Deficiencies: Code - Category Description

0630 - Launch arrangt. for Starboard lifeboat releasing mechanism

survival craft inoperable.

Ship Name: PACDUKE Ship Type: Bulk Carrier

IMO Number: 7374620 Flag: Liberia

Date Detained: 8/17/99 Class Society: American Bureau of Shipping

Port: Seattle, Washington Company(s): Owners, Operators or Managers

Lasco Shipping Co.

Trans Pacific Shipping Company

Deficiencies: Code - Category Description

0630 - Launch arrangt. for Lifeboat releasing gear mechanisms

survival craft

Ship Name: PANDORA P Ship Type: Bulk Carrier

IMO Number: 8100870 Flag: Panama

Date Detained: 8/26/99 Class Society: Lloyd's Register of Shipping

Port: New Haven, Connecticut Company(s): Owners, Operators or Managers

Seer Shipping Corp

Deficiencies: Code - Category Description

2020 - Fire drills The crew was unable to perform a satisfactory

fire drill.

1730 - Oily-water separating The oily-water separator was inoperable.

equipment

Ship Name: PANLI Ship Type: Bulk Carrier

IMO Number: 8015661 Flag: Cyprus

Date Detained: 8/30/99 Class Society: Det Norske Veritas

Port: **Portland, Oregon** Company(s): Owners, Operators or Managers

Pan Liberty Navigation Co. Ltd. Sea Pioneer Shipping Corp.

Deficiencies: Code - Category Description

0725 - Fixed fire extinguishing Fixed, CO2 fire extinguishing system was

installation inoperative.

Ship Name: **RENATE SCHULTE** Ship Type: **Containership**

IMO Number: 9057147 Flag: Liberia

Date Detained: 8/20/99 Class Society: Germanischer Lloyd

Port: Los Angeles, California Company(s): Owners, Operators or Managers

Southwet Shipping Inc.

Deficiencies: Code - Category Description

0999 - Other (Safety In General) Aft fuel oil tank fractured, and leaking

hazardous amount of oil into the engine room

bilge.

Ship Name: SAGAMI Ship Type: Refrigerated Cargo Carrier

IMO Number: 9087910 Flag: Japan

Date Detained: 8/26/99 Class Society: Nippon Kaiji Kyokai

Port: American Samoa Company(s): Owners, Operators or Managers

Wakoh Shipping Company

Deficiencies: Code - Category Description

2020 - Fire drills Crew unable to conduct a proper fire drill.

Ship Name: SANTA BARBARA Ship Type: Containership

IMO Number: 9017032 Flag: Liberia

Date Detained: 8/17/99 Class Society: Nippon Kaiji Kyokai

Port: Long Beach, California Company(s): Owners, Operators or Managers

Gregory Shipping Inc.

Deficiencies: Code - Category Description

0630 - Launch arrangt. for

survival craft

Lifeboat falls releasing gear inoperable.

Ship Name: SEALINK EXPRESS Ship Type: General Dry Cargo Ship

IMO Number: 6805608 Flag: Panama

Date Detained: 8/4/99 Class Society: International Register of Shipping

Port: San Juan, Puerto Rico Company(s): Owners, Operators or Managers

Sealink, Inc.

Deficiencies: <u>Code - Category</u> <u>Description</u>

1730 - Oily-water separating Oily-water separator inoperable.

equipment

Ship Name: STAR SEA RAINBOW Ship Type: Bulk Carrier

IMO Number: 9172961 Flag: Panama

Date Detained: 8/7/99 Class Society: Bureau Veritas

Port: **Portland, Oregon** Company(s): Owners, Operators or Managers

Far-East Transport Co. Ltd.

Deficiencies: Code - Category Description

2525 - Masters responsibility and Safety Management System was not reviewed

authority by Master or Chief Engineer.

Ship Name: STRAUME Ship Type: Refrigerated Cargo Carrier

IMO Number: 7436258 Flag: Latvia

Date Detained: 8/14/99 Class Society: Russian Maritime Register of Shipping

Port: Anchorage, Alaska Company(s): Owners, Operators or Managers

Eastern Alliance, S.A.

Deficiencies: Code - Category Description

> machinery leaking an excessive amount of oil; excessive water leaking from vital engine cooling piping systems; hazardous levels of oil

in the bilge.

2020 - Fire drills Crew unable to perform a satisfactory fire 0936 - Steering gear Steering pump leaking excessive amounts of

0730 - Appliances (general Portable fire extinguishers improperly

equipment) maintained and inoperable.

1270 - Doors Watertight door to CO2 room inoperable and

not watertight.

Ship Name: YALAZ Ship Type: Bulk Carrier

IMO Number: **7507186** Flag: **Turkey**

Date Detained: 8/18/99 Class Society: American Bureau of Shipping

Port: San Francisco, California Company(s): Owners, Operators or Managers

Akarser Denizciklik

Deficiencies: Code - Category Description

0630 - Launch arrangt. for The port and staboard lifeboats could not be

survival craft lowered.

0113 - Cargo ship safety radio Cargo Ship Safety Radio Certificate was

expired..